

Informations for Platinum 100 I M8 with Windows XP Professional SB Preload

The following drivers are unsigned:

1. MB MPL Snow Hill LC - S3210SHLC (400533)
 - - onboard VGA / Matrox G200e
2. I/O Card PCIe Tragant 89129 2xser 1x par (233833), optional
 - - NetMos PCI ECP Parallel Port (LPT3)
 - - NetMos PCI Serial Port (Com3)
 - - NetMos PCI Serial Port (Com4)

Installation of these drivers requires user intervention.

After the first logon, when the Hardware Update Wizard pops up, take the following steps:

- Can Windows connect to Windows update to search for software?
Select [No, not this time] and klick [next]
- Install the software automatically , klick [next]
- Hardware installation popup:
The software you are installing for this hardware: ..
has not passed Windows Logo testing ..
Select [Continue Anyway]
- Finish

Repeat these steps for each of the mentioned drivers.

During installation of the graphics driver the screen will be blanked for a short time.